In the Program

Allenstown 069/056	US 3	Over	Buck St., Suncook River	Owner NHDOT	Spans	Type DT	Wide 30.0	Long 394	Notes Serious Condition. CWIP	Action Replace	Cost \$13,653,049	Year 2006
Alstead 073/163	NH123A	Over	WARREN BROOK	NHDOT	1	СТВ	29.1	34	Deck Poor. Additional damage during October	Rehab	\$500,000	2007
Alton 186/155	NH 28	Over	MERRYMEETING RIVER	NHDOT	1	CRF	27.3	31	flood. Poor Condition.	Replace	\$1,390,000	2007
Andover 058/103	NH 11,NH 4A	Over	US 4,NHRR(ABD)	NHDOT	6	IB-C	34.5	264	Deck Serious.	Replace	\$2,008,000	2008
Bartlett 188/123	US302	Over	NHRR(CONWAY SCENIC LINE)	NHDOT	3	IB-C	31.0	149	Serious Condition.	Replace	\$4,313,750	2007
Bartlett 189/129	US302	Over	SACO RIVER	NHDOT	2	TPG	27.5	222	Serious Condition.	Replace	\$4,313,750	2007
Bedford 189/121	US 3	Over	FEE TPK	Turnpike Bureau	u, 2	IB-C	41.5	150	Deck and Substructure Poor.	Replace	\$5,775,000	2010
Bow 135/160	I-93,FEE TPK SB	Over	I-89,TURKEY RIVER	Turnpike Bureau	u, 5	IB-C	35.8	244	Deck and Substructure Poor.	Replace	\$7,000,000	2014
Bow 136/155	GRANDVIEW ROAD	Over	I-93,FEE TPK	Turnpike Bureau NHDOT	J, 2	IB-C	39.7	331	Deck Poor.	Rehab	\$962,000	2007
Bow 136/160	I-93,FEE TPK NB	Over	I-89,TURKEY RIVER	Turnpike Bureau NHDOT	u, 5	IB-C	47.8	244	Deck and Substructure Poor.	Replace	\$7,000,000	2014
Clarksville 090/120	NH145	Over	CONNECTICUT RIVER	NHDOT	3	ТВ	25.3	92	Serious Condition. Temporary supports in place. Winterset Inc. won bid. Project 13028	Replace	\$3,455,128	2006
Colebrook 177/068	NH 26	Over	MOHAWK RIVER	NHDOT	1	TPG	26.5	70	Girders heavily rusted.	Replace	\$4,400,000	2007
Colebrook 201/062	NH 26	Over	MOHAWK RIVER	NHDOT	1	TPG	26.5	89	Girders heavily rusted.	Replace	\$5,600,000	2007
Colebrook 202/059	NH 26	Over	BALSAM POND BROOK	NHDOT	1	CS	26.0	26	Poor Condition.	Replace	\$1,600,000	2007
Concord 142/116	Delta Drive	Over	I-93,US 4	NHDOT	4	IB-C	38.6	192	Deck Poor.	Replace	\$1,000,000	2014
Concord 163/106	I-93,FEE TPK	Over	NH 9(LOUDON ROAD)	Turnpike Bureau	u, 1	IB-C	86.8	86	Deck Serious.	Replace	\$5,000,000	2014
Concord 203/087	NH 3A	Over	I-93,FEE TPK	Turnpike Bureau NHDOT	J, 4	IB-C	63.5	217	Deck and Substructure Poor.	Replace	\$4,000,000	2014
Dover 109/106	NH 9	Over	BMRR	NHDOT	2	IB-C	31.1	75	Deck Poor.	Replace	\$4,265,000	2009
Enfield 077/139	MAIN STREET	Over	MASCOMA LAKE	NHDOT	5	IB-C	27.4	323	Poor Condition, Posted 'Weight Limit 15 Tons'.	Replace	\$7,250,000	2008
Hampton 162/142	NH 27	Over	BMRR	NHDOT	2	ТВ	39.7	37	Low Capacity, Posted 'Weight Limit 11 Tons'. CWIP	Rehab	\$899,418	2006

In the Program

Hampton 235/025	NH 1A	Over	HAMPTON RIVER	Owner NHDOT	Spans 13	Type BAS	Wide 33.5	Long 1199	Notes Deck Poor. Mechanical and electrical repairs 2001, 2002, and 2003. Study being started. Also paint in 2005	Action Rehab	Cost \$8,000,000	Year 2007
Hancock 138/110	NH137	Over	MOOSE BROOK	NHDOT	1	IB-C	31.8	75	Deck Poor.	Rehab	\$735,000	2006
Hanover 040/043	NH 10	Over	MINK BROOK	NHDOT	1	СТВ	41.3	33	Poor Superstructure. Considered for Design Build Contract.	Replace	\$1,625,000	2006
Haverhill 215/158	MILL STREET	Over	NHRR(ABD)	NHDOT	7	ТВ	18.8	147	Low Capacity, Posted 'Weight Limit 6 Tons'. Bridge maintenance looking at rehab.	Rehab	\$325,000	2005
Hooksett 069/162	PINE STREET	Over	I-93,FEE TPK	Turnpike Bureau NHDOT	, 2	IB-C	56.7	269	Deck Poor.	Rehab	\$867,800	2006
Hopkinton 089/114	NH127	Over	SPILLWAY CHANNEL	NHDOT	3	IB-C	32.0	280	Deck Poor.	Rehab	\$1,500,000	2009
Lebanon 058/127	US 4	Over	CONNECTICUT RIVER	NHDOT	3	HT	26.0	392	Deck Serious. Bridge Maintenance Steel Repairs 2005	Rehab	\$5,250,000	2014
Lebanon 156/117	I-89 NB	Over	HARDY HILL ROAD	NHDOT	1	IB-C	42.3	45	Deck Poor.	Rehab	\$2,000,000	2008
Lebanon 188/126	US 4	Over	NHRR(ABD),MASCOMA RIVER	NHDOT	6	DPG	31.0	463	Deck and Floorbeams Poor.	Rehab	\$1,022,500	2011
Londonderry 096/163	I-93 SB	Over	BMRR (ABD)	NHDOT	3	IB-C	47.8	142	Deck Serious.	Replace	\$1,200,000	2011
Londonderry 097/163	I-93 NB	Over	BMRR (ABD)	NHDOT	3	IB-C	51.8	150	Deck and Substructure Serious.	Replace	\$1,200,000	2011
Londonderry 099/160	I-93 SB	Over	NH 28	NHDOT	3	IB-C	43.8	153	Deck Poor.	Replace	\$1,200,000	2011
Londonderry 100/160	I-93 NB	Over	NH 28	NHDOT	3	IB-C	43.8	150	Deck Poor.	Replace	\$1,200,000	2011
Madbury 114/084	NH155	Over	BMRR	NHDOT	3	СТВ	34.5	131	Serious Condition. CWIP	Replace	\$8,129,171	2006
Manchester 134/067	I-293,FEE TPK	Over	GRANITE STREET	Turnpike Bureau NHDOT	, 1	IB-C	77.8	73	Deck Serious. CWIP	Replace	\$22,900,000	2005
Manchester 144/066	I-293,FEE TPK	Over	N BR PISCATAQUOG RIVER	Turnpike Bureau NHDOT	, 3	IB-C	84.9	148	Deck and Substructure Poor.	Rehab	\$2,000,000	2013
Manchester 146/064	I-293,FEE TPK	Over	S BR PISCATAQUOG RIVER	Turnpike Bureau NHDOT	, 3	IB-C	69.8	213	Deck Poor.	Rehab	\$2,000,000	2013
Manchester 146/065	I-293,FEE TPK SPUR	Over	S BR PISCATAQUOG RIVER	Turnpike Bureau NHDOT	, 3	IB-C	25.8	216	Deck Poor.	Rehab	\$2,000,000	2013
Manchester 149/063	I-293,FEE TPK	Over	SPUR D	Turnpike Bureau NHDOT	, 3	IB-C	73.8	149	Deck Poor.	Rehab	\$2,000,000	2013
Manchester 153/061	I-293 RAMP	Over	I-293,FEE TPK	Turnpike Bureau NHDOT	, 4	IB-C	25.8	252	Deck Poor.	Rehab	\$2,000,000	2013

In the Program

Manchester 166/124	ISLAND POND ROAD	Over I-93 SB,I-293 WB	Owner NHDOT	Spans 3	Type IB-C	Wide 38.0	Long 170	Notes Deck and Substructure Poor.	Action Rehab	Cost \$2,000,000	Year 2011
Manchester 166/125	ISLAND POND ROAD	Over I-93 NB,I-293 EB	NHDOT	3	IB-C	38.0	170	Deck Serious, Substructure Poor.	Rehab	\$2,000,000	2011
Merrimack 111/115	FEE TPK	Over SOUHEGAN RIVER	Turnpike Bureau NHDOT	ı, 3	IB-C	92.5	229	Deck and Substructure Poor.	Rehab	\$7,501,000	2007
Monroe 081/106	MCINDOES STREET	Over CONNECTICUT RIVER	NHDOT	1	HT	22.2	308	Low Capacity, Posted 'Weight Limit 3 Tons'.	Rehab	\$2,391,861	2006
New Castle 066/071	NH 1-B	Over LITTLE HARBOR	NHDOT	6	BAS	30.8	253	Monitor Exposed Steel Piles, Pile Repair by Bridge Maintenance, Contract Paint in 2000, some holes in stringers.	Rehab	\$4,750,000	2012
New Ipswich 157/093	NH123,NH124	Over SOUHEGAN RIVER	NHDOT	9	IB-C	30.2	135	Poor Condition.	Replace	\$2,100,000	2010
New London 124/058	I-89 SB	Over KING HILL ROAD	NHDOT	1	IB-C	43.8	88	Deck Poor.	Rehab	\$1,200,000	2014
New London 124/059	I-89 NB	Over KING HILL ROAD	NHDOT	1	IB-C	43.8	88	Deck Serious.	Rehab	\$1,200,000	2014
Ossipee 137/297	NH 16,NH 25	Over BEARCAMP RIVER	NHDOT	5	IB-C	33.2	396	Superstructure Poor.	Rehab	\$2,000,000	2012
Ossipee 137/299	NH 16,NH 25	Over RELIEF BEARCAMP RIVER	NHDOT	4	IB-C	33.2	172	Poor Deck and Substructure.	Rehab	\$2,000,000	2012
Ossipee 152/268	NH 16,NH 25	Over LOVELL RIVER	NHDOT	1	IB-C	34.5	62	Deck poor. Also listed for Betterment Funding in 2007.	Rehab	\$2,000,000	2012
Plaistow 105/028	NH121	Over BMRR,LITTLE RIVER,ROAD	NHDOT	10	IB-C	31.0	518	Serious Condition. Under Construction	Replace	\$9,158,338	2005
Portsmouth 154/101	NH 33	Over BMRR	NHDOT	1	IB-C	32.0	45	Serious Condition. Municipally Managed Project.	Replace	\$5,200,000	2008
Portsmouth 173/071	US 1 SB	Over US 1 BYPASS	NHDOT	4	IB-C	26.0	182	Deck Poor.	Replace	\$2,000,000	2013
Portsmouth 183/087	NH 33	Over US 1 BYPASS	NHDOT	4	IB-C	30.1	123	Deck Poor.	Replace	\$2,000,000	2013
Portsmouth 188/097	ISLINGTON STREET	Over US 1 BYPASS	NHDOT	4	IB-C	31.7	123	Deck Poor.	Replace	\$2,000,000	2013
Portsmouth 205/116	WOODBURY AVENUE	Over US 1 BYPASS	NHDOT	1	CRF	52.0	90	Poor Condition.	Replace	\$2,000,000	2010
Portsmouth 211/114	STARK STREET	Over US 1 BYPASS	NHDOT	4	IB-C	30.7	123	Deck Poor.	Replace	\$2,000,000	2010
Portsmouth 227/112	MAPLEWOOD AVENUE	Over US 1 BYPASS	NHDOT	4	IB-C	30.1	161	Deck Poor.	Rehab	\$2,000,000	2010

In the Program

Portsmouth 247/084	US 1	Over PISCATAQUA RIVER	Owner NHDOT	Spans 13	Type LIFT	Wide 29.0	Long 1201	Notes Severe rusting. 1999 project to install barrier gates. 2004 interim structural repairs. Major Rehabilitation needed	Action Rehab	Cost \$31,700,000	Year 2007
Portsmouth 251/108	US 1 BYPASS	Over PISCATAQUA RIVER & RR	Interstate Bridge Auth.	27	LIFT	36.0	2804	Deck Poor.	Rehab	\$17,490,000	2012
Rochester 157/110	SP TPK,NH 16 NB	Over NH125	Turnpike Bureau, NHDOT	3	IB-C	47.3	153	Deck Poor. Project may be delayed?	Replace	\$14,716,972	2010
Rochester 158/110	SP TPK,NH 16 SB	Over NH125	Turnpike Bureau, NHDOT	3	IB-C	47.8	153	Deck Poor.	Replace	\$15,096,348	2008
Rye 252/156	NH 1A	Over SEAVEYS CREEK	NHDOT	8	ТВ	30.0	145	Poor Condition.	Replace	\$3,895,000	2009
Salem 068/078	I-93 SB	Over PELHAM ROAD	NHDOT	3	IB-C	47.8	127	Deck Serious, Substructure Poor.	Replace	\$6,050,000	2009
Salem 070/079	I-93 NB	Over PELHAM ROAD	NHDOT	3	IB-C	43.8	134	Deck and Substructure Poor.	Replace	\$6,050,000	2009
Salem 073/063	I-93 SB	Over NH 38	NHDOT	3	IB-C	43.8	139	Serious Condition.	Replace	\$9,900,000	2009
Salem 077/063	I-93 NB	Over NH 38	NHDOT	3	IB-C	43.8	142	Deck Serious.	Replace	\$9,900,000	2009
Salem 080/056	I-93(RAMP D)	Over I-93 SB	NHDOT	3	IB-C	25.0	158	Deck Poor.	Replace	\$2,000,000	2007
Salem 081/055	I-93(RAMP B)	Over I-93 SB	NHDOT	3	IB-C	43.0	163	Deck Poor.	Replace	\$2,000,000	2007
Salem 081/058	I-93(RAMP D)	Over I-93 NB	NHDOT	3	IB-C	25.0	153	Deck Serious.	Replace	\$2,000,000	2007
Salem 082/057	I-93(RAMP B)	Over I-93 NB	NHDOT	3	IB-C	43.0	155	Deck Serious.	Replace	\$2,000,000	2007
Salem 082/061	I-93(RAMP B)	Over SOUTH POLICY ROAD	NHDOT	3	IB-C	43.0	146	Deck Serious.	Replace	\$2,000,000	2007
Salem 083/061	I-93(RAMP D)	Over SOUTH POLICY ROAD	NHDOT	3	IB-C	26.7	146	Deck Poor.	Replace	\$2,000,000	2007
Salem 084/061	I-93(RAMP A)	Over SOUTH POLICY ROAD	NHDOT	3	IB-C	55.0	151	Deck Serious.	Replace	\$2,000,000	2007
Salem 089/052	CROSS STREET	Over I-93	NHDOT	4	IB-C	38.3	342	Deck Poor.	Replace	\$12,100,000	2007
Sanbornton 231/073	US 3	Over WINNISQUAM LAKE	NHDOT	4	IB-C	52.4	474	Deck Poor.	Rehab	\$3,883,253	2006
Stratham 122/096	WINNICUT ROAD	Over WINNICUT RIVER	NHDOT	3	CRF	29.4	67	Poor condition, Bridge Maintenance to upgrade.	Rehab	\$750,000	2006
Sullivan 093/061	NH 9	Over OTTER BROOK	NHDOT	2	СТВ	27.8	92	Superstructure Poor. October flood damage	Replace	\$2,200,000	2014
Walpole 062/052	BRIDGE STREET	Over CONNECTICUT RIVER	NHDOT	2	CA	32.5	230	repaired. Serious Condition, Posted 'Weight Limit 10 Tons'.	Rehab	\$2,865,000	2011

In the Program

Warner 243/166	I-89 SB Over WARNER RIVER	Owner NHDOT	Spans Typ 3 IB-0		Long 159	Notes Deck Serious.	Action Rehab	Cost Ye \$3,500,000 20	
Warner 244/167	I-89 NB Over WARNER RIVER	NHDOT	3 IB-0	C 42.3	159	Deck Serious.	Rehab	\$3,500,000 20)07
Warren 109/048	NH 25,NH118 Over BAKER RIVER	NHDOT	1 TPC	G 27.2	104	Serious Condition. Bids received.	Replace	\$3,505,330 20)06
Winchester 152/181	NH 10 Over ASHUELOT RIVER	NHDOT	3 IB-0	31.3	181	Deck Poor.	Replace	\$4,000,000 20)10
Windham 134/101	I-93 SB Over NH111	NHDOT	3 IB-0	C 43.8	168	Deck Serious.	Replace	\$8,000,000 20	800
Windham 135/090	I-93 SB Over NH111A	NHDOT	3 IB-0	C 43.8	160	Deck Seroius.	Replace	\$3,000,000 20)09
Wolfeboro 112/110	NH 28,NH109 Over SMITH RIVER	NHDOT	1 IB-0	30.9	30	Deck Poor. CWIP	Replace	\$3,539,990 20)06
						87 Bridges Total C	ost:	\$386,682,657	

Monitor and Keep in Service

Andover 179/146	VALLEY ROAD	Over	NHRR(ABD)	Owner NHDOT	Spans 5	Type TB	Wide 16.5	Long 90	Notes Low Capacity, Posted 'Weight Limit 15 Tons'. Bridge Maintenance rehab	
Conway 167/067	EAST SIDE ROAD	Over	SACO RIVER	NHDOT	2	TB-C	18.8	227	completed 2002. Covered Bridge, Posted 'Weight Limit 6 Tons'. Fire supression installation, 2002	
Cornish 064/108	CORNISH TOLL BR RD	Over	CONNECTICUT RIVER	NHDOT	2	тв-с	20.7	449	Covered Bridge, Posted 'Weight Limit 10 Tons'. Fire supression installation, 2002	
Dover 200/023	ROAD	Over	LITTLE BAY	Turnpike Bureau NHDOT	, 9	HT	30.6	1585	Poor Condition, Study Project Underway, Closed to vehicular traffic.	
Hancock 158/068	FORREST ROAD	Over	CONTOOCOOK RIVER	NHDOT	1	тв-с	26.0	88	Covered Bridge, Posted 'Weight Limit 8 Tons'. Fire supression installation, 2002	
Jackson 148/050	NH 16A	Over	ELLIS RIVER	NHDOT	1	TB-C	25.8	121	Covered Bridge, Posted 'Weight Limit 6 Tons'. Rehab 2004	Rehab
Laconia 126/163	CENTENARY AVENUE	Over	NHRR	NHDOT	7	ТВ	22.6	121	Low Capacity, Posted 'Weight Limit 7 Tons'.	
Lebanon 192/129	PAYNE ROAD	Over	NHRR (ABD)	NHDOT	2	TB	18.0	54	Low Capacity, Posted 'Weight Limit 15 Tons'.	
Lincoln 149/110	FLUME BUS ROUTE	Over	PEMIGEWASSET RIVER	NHDRED	1	TB-C	16.3	52	Covered Bridge, Low Capacity (Flume Bus use Only).	
New Hampton 240/104	SMITHS CROSSING	Over	NHRR	NHDOT	3	TB	16.0	82	Deck Poor, Low Capacity, Posted 'Weight Limit 6 Tons'.	
Pittsburg 099/034	MURPHY DAM ROAD	Over	DAM SPILLWAY	NHDES	1	BGB	20.5	38	Low Capacity, Posted 'Weight Limit 15 Tons'.	
Raymond 083/154	DUDLEY ROAD	Over	LAMPREY RIVER	NHDOT	2	CS	21.0	52	Wings Settled, Posted 'Weight Limit 6 Tons'.	
									12 Bridges	

12 Bridges

Needs to be added to the Program

Colebrook 039/107	NH 26 Over	CONNECTICUT RIVER	Owner NHDOT	Spans 2	Type IB-C	Wide 30.5	Long 164	Notes Deck Poor	Action Rehab	Cost \$900,000
Farmington 096/140	NH153 Over	COCHECO RIVER	NHDOT	2	IB-C	40.5	48	Poor Condition.	Replace	\$1,652,400
Franklin 162/100	NHRR(ABD) Over	NH127	NHDOT	1	TPG	0.0	72	Deck holed, Abutments Poor.	Remove	\$400,000
New Boston 103/103	NH 13 Over	S BR PISCATAQUOG RIVER	NHDOT	1	CRF	31.3	62	Poor Condition.	Rehab	\$750,000
Pelham 110/090	GAGE HILL ROAD Over	BEAVER BROOK	NHDOT	2	MA	35.7	46	Monitor Stonework, poor condition	Replace	\$2,000,000
Sanbornton 127/099	I-93 NB Over	SALMON BROOK	NHDOT	1	СВ	0.0	28	Poor areas in Concrete Box.	Rehab	\$500,000
Stewartstown 121/114	NH145 Over	BISHOP BROOK	NHDOT	1	IB-C	23.0	42	Substructure in Serious Condition.	Replace	\$910,000
Warner 144/056	NH103 Over	WARNER RIVER	NHDOT	1	TPG	32.0	81	Deck Poor. New paint 2006.	Rehab	\$400,000
Wilton 129/126	NH 31 Over	SOUHEGAN RIVER	NHDOT	1	IB-C	38.5	80	Deck Poor.	Rehab	\$750,000
Winchester 113/077	NH119 Over	ASHUELOT RIVER	NHDOT	3	IB-C	43.5	194	Deck Poor.	Rehab	\$2,000,000
								10 Bridges Total (Cost:	\$10,262,400

To be addressed by Bridge Maintenance

Acworth 113/064	NH123A	Over	BOWERS BROOK	Owner NHDOT	Spans 1	Type Jack	Wide 27.3	Long 17	Notes Poor Condition. Additional damage during October flood event. Listed in program for 2007, \$600,000.00. Installation to be done by Bridge	Action Replace	Year 2007
Andover 050/093	NH 11	Over	BLACKWATER RIVER	NHDOT	2	IB-C	48.5	124	Maintenance Deck Poor. Pier repaired 2005 by Bridge Maintenance.	Rehab	WTP
Chesterfield 080/120	BROOK STREET	Over	CATSBANE BROOK	NHDOT	1	IB-C	26.7	41	Deck Poor.	Rehab	WTP
Croydon 140/120	NH 10	Over	ASH SWAMP BROOK	NHDOT	1	CS	31.0	24	Slab Poor.	Rehab	WTP
Gilsum 062/136	SURRY ROAD	Over	DART BROOK	NHDOT	1	CS	31.7	18	Substructure poor, October flood damage.	Rehab	2006
Grafton 130/126	US 4	Over	TEWKSBURY POND OUTLET	NHDOT	1	CS	36.1	22	Slab Poor.	Rehab	WTP
Hancock 097/077	NH137	Over	DAVIS BROOK	NHDOT	1	MP-A	0.0	12	Severe corrosion at base of corrugated arch plates.	Rehab	WTP
Harrisville 056/058	CHESHAM ROAD	Over	MINNEWAWA BROOK	NHDOT	3	CS	27.0	90	Slab Poor.	Rehab	WTP
Henniker 101/116	US202,NH 9	Over	LIBERTY HILL ROAD	NHDOT	1	CRF	46.7	78	Centerline Frame in poor condition.	Rehab	WTP
Littleton 200/137	NH135	Over	COW BROOK	NHDOT	1	MP	0.0	10	Pipe Poor	Rehab	WTP
New Ipswich 113/074	SMITHVILLE ROAD	Over	WEST BR SOUHEGAN RIVER	NHDOT	1	MP	0.0	12	Rusting of Corrugated Steel Pipe.	Rehab	2006
Stewartstown 079/151	US 3	Over	BISHOP BROOK	NHDOT	1	Jack	31.2	29	Poor Condition.	Rehab	WTP
Stratham 075/114	NH 33 EB,NH108 NB	Over	MILL BROOK	NHDOT	1	MP	62.0	11	Pipe in poor condition	Rehab	WTP
Swanzey 149/072	NH 32	Over	MARTIN BROOK	NHDOT	1	CS	23.7	27	Poor Condition.	Rehab	WTP
Swanzey 150/056	NH 32	Over	MARTIN BROOK	NHDOT	1	CS	25.0	16	Poor Condition.	Rehab	WTP
Temple 094/114	NH101	Over	BLOOD BROOK	NHDOT	1	CS	51.0	24	Poor Condition.	Rehab	WTP
Warner 254/180	NH127	Over	WARNER RIVER	NHDOT	3	IB-C	28.2	123	Deck Poor	Rehab	\$900,000
Westmoreland 111/072	NH 63	Over	PARTRIDGE BROOK	NHDOT	1	СВ	27.0	24	Poor Condition.	Rehab	WTP
Wilmot 139/083	NH 4A	Over	KIMPTON BROOK	NHDOT	1	CS	35.7	23	Poor Condition.	Rehab	WTP
Wilton 102/095	NH 31	Over	BLOOD BROOK	NHDOT	1	CRF	29.6	46	Poor Condition.	Rehab	WTP

To be addressed by Bridge Maintenance

Winchester 065/102 NH119 Over BROAD BROOK NHDOT 1 CRF 41.0 21 Poor Condition. Rehab WTP

21 Bridges Total Cost: \$900,000

To be addressed by Rail and Transit

		Owner	Spans	Type	Wide	Long	Notes	Action	Cost	Year
Bennington 093/094	BMRR(ABD) Over ANTRIM ROAD	NHDOT	1	TB	0.0	19	Rail line not in service,	Rehab		WTP
							Severe Overheight Damage.			
Seabrook 136/071	BMRR(ABD) Over WALTON ROAD	NHDOT	1	IB-W	10.0	24	Overheight collision damage to girder	Rehab		WTP
							2 Bridges			

Waiting Municipal Action

			Owner	Spans		Wide	Long	Notes	Action	Cost	Year
Durham 093/080	BENNETT ROAD	Over BMRR	NHDOT	1	ТВ	21.5	33	Low Capacity, Posted 'Weight Limit 10 Tons'. Rehab by Bridge Maintenance, 2002.			
Exeter 088/076	PARK STREET	Over BMRR	NHDOT	1	LT	26.6	63	Low Capacity, Posted 'Weight Limit 6 Tons'. Bridge Maintenance replaced floor and several steel members, 2002, 2003.			
Madbury 119/074	PERKINS ROAD	Over BMRR	NHDOT	1	ТВ	21.8	31	Low Capacity, Posted 'Weight Limit 14 Tons'. Bridge Maintenance replaced deck, 2002.			
Nashua 115/120	BALDWIN STREET	Over BMRR	NHDOT	3	ТВ	19.6	73	Deck Poor, Low Capacity, Posted 'Weight Limit 6 Tons'. Part of the Broad Sreet Parkway Project, Municipally Managed.	Replace	\$4,684,764	2010
Newfields 130/083	NEW ROAD	Over BMRR	NHDOT	2	TB	18.9	41	Low Capacity, Posted 'Weight Limit 6 Tons'.			
Newton 064/107	POND ROAD	Over BMRR	NHDOT	1	ТВ	25.0	41	Low Capacity, Posted 'Weight Limit 8 Tons'. Bridge Maintenance replacing deck and stringers, 2003.			
North Hampton 130/064	CEDAR ROAD	Over BMRR	NHDOT	1	ТВ	21.0	34	Low Capacity, Posted 'Weight Limit 11 Tons'. Repairs by Bridge Maintenance 2002.			
Rollinsford 069/046	OAK STREET	Over BMRR	NHDOT	1	LT	26.5	65	Serious Condition, Posted 'Weight Limit 6 Tons'.			
								8 Bridges Total Co	ost:	\$4,684,764	